

PostScript Picture  
(Edelbrock B/W Logo.eps)

---

## **Important Notice**

These cylinder heads are equipped with valve spring cups. Due to the diameter of the valve spring cups, it may be necessary to clearance the headbolt washer #1. The #1 headbolt is called out in your instruction sheet (see bolt torque sequence). The headbolt washer in the #1 location is the only washer that may require clearancing. This will allow the headbolt washers to seat properly to the cylinder head. See *Figure 1*.

